

Section IV - Fire and Explosion Hazard Data

Flash Point (Method Used) 645°	Flammable Limits N/A	LEL N/A	UEL N/A
Extinguishing Media Water-Foam-CO2			
Special Fire Fighting Procedures None			
Unusual Fire and Explosion Hazards None			

(Reproduce locally)

OSHA 174, Sept. 1985

Section V - Reactivity Data

Stability	Unstable		Conditions to Avoid Very Strong Oxidizing Agents
	Stable	X	
Incompatibility (<i>Materials to Avoid</i>) None Known			
Hazardous Decomposition or Byproducts None			
Hazardous Polymerization	May Occur		Conditions to Avoid
	Will Not Occur	X	

Section VI - Health Hazard Data

Route(s) of Entry:	Inhalation? No	Skin? No	Ingestion? Yes
Health Hazards (<i>Acute and Chronic</i>) None			
Carcinogenicity: None	NTP?	IARC Monographs?	OSHA Regulated?
Signs and Symptoms of Exposure None			
Medical Conditions Generally Aggravated by Exposure None			
Emergency and First Aid Procedures None			

Section VII - Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled
<p>As the end product (lumber) – Collect and restack Raw Material – Collect back into box for use Saw Swarf (dust) – Brush up and dispose to landfill</p>
Waste Disposal Method Dispose to sanitary landfill
Precautions to Be taken in Handling and Storing No special precautions – Good housekeeping practice should be followed
Other Precautions None

Section VIII - Control Measures

Respiratory Protection (<i>Specify Type</i>) N/A		
Ventilation	Local Exhaust When cutting	Special None
	Mechanical (<i>General</i>) N/A	Other None
Protective Gloves When cutting	Eye Protection When cutting	
Other Protective Clothing or Equipment None		
Work/Hygienic Practices Normal Hygiene		

* U.S.G.P.O.: 1986 - 491 - 529/45775